

Play Area / Equipment Operational Inspection

LLANBLETHIAN PARK PLAY AREA

Complete

Score	7 / 8 (87.5%)	Flagged items	0	Actions	0
-------	---------------	---------------	---	---------	---

Document No. 000013

Audit Title LLANBLETHIAN PARK PLAY AREA

Client / Site COWBRIDGE TOWN COUNCIL

Conducted on 31.08.2023 08:50 BST

Prepared by Jerry Widdas

Location Llanblethian

Personnel

Audit

7 / 8 (87.5%)

GENERAL SITE DESCRIPTION

1 / 1 (100%)

Detail:

Yes

Llanblethian Play Area is an open playing field in a quiet area of the town, the play area is accessed across grass from the access gates located on the road.

The play equipment has been installed within the past few years and is all in very good condition and installed onto rubber safety surfacing

Lappset multiplayer unit installed April 2018

Lappset flat seat swing installed April 2018

Lappset nest swing installed April 2018

Lappset spring rockers installed April 2018

Bank slide installation date unknown

Football goal installed June 2023

Ball shoot installation date unknown



Photo 1



Photo 2




Photo 3



Photo 4



Photo 5



Photo 6




Photo 7



Photo 8



Photo 9

ITEM

6 / 6 (100%)

Manufacturer identification and date of installation

Yes

All play equipment listed above

Item Condition

Safe

Safety Surfacing

Safe

Equipment Findings

Safe

The access gates are showing signs of advanced rot which is preventing proper opening and closing




Photo 10

Safety Surfacing Findings

Safe

All safety surfaces are in good condition with no damage showing

Recommendations


Yes

Schedule inspection for October 2nd

Other comments

0 / 1 (0%)

Inspector Sign Off



Jeremy Widdas OP1200
31.08.2023 08:51 BST

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10