

Play Area / Equipment Operational Inspection

LLANBLETHIAN PARK PLAY AREA

Complete

Score	7 / 8 (87.5%)	Flagged items	0	Actions	0
-------	---------------	---------------	---	---------	---

Document No. 000013

Audit Title LLANBLETHIAN PARK PLAY AREA



Client / Site COWBRIDGE TOWN COUNCIL

Conducted on 04.06.2024 22:30 BST

Prepared by Jerry Widdas

Location Llanblethian

Personnel

Audit	7 / 8 (87.5%)
GENERAL SITE DESCRIPTION	1 / 1 (100%)
Detail: Llanblethian Play Area is an open playing field in a quiet area of the town, the play area is accessed across grass from the access gates located on the road. The play equipment has been installed within the past few years and is all in very good condition and installed onto rubber safety surfacing Lappset multiplayer unit installed April 2018 Lappset flat seat swing installed April 2018 Lappset nest swing installed April 2018 Lappset spring rockers installed April 2018 Bank slide installation date unknown Football goal installed June 2023 Ball shoot installation date unknown	Yes
         	
ITEM	6 / 6 (100%)
Manufacturer identification and date of installation All play equipment listed above	Yes
Item Condition	Safe
Safety Surfacing A moss killer was applied Moss starting to disappear	Safe
  	

Equipment Findings

Safe

The access gates are showing signs of advanced rot which is preventing proper opening and closing
Capstones on the gate pillars are very loose and falling off



Photo 14



Photo 15



Photo 16

Safety Surfacing Findings

Safe

All safety surfaces are in good condition with no damage showing

Recommendations

Yes

Schedule inspection for 7th July

Other comments

0 / 1 (0%)

Inspector Sign Off

Jeremy Widdas OP9635
01.09.2024 21:44 BST

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16