



Play Area / Equipment Operational Inspection

LLANBLETHIAN PARK PLAY AREA

Complete

Score	7 / 8 (87.5%)	Flagged items	0	Actions	0
Document No.	000013				
Audit Title	LLANBLETHIAN PARK PLAY AREA				
Client / Site	COWBRIDGE TOWN COUNCIL				
Conducted on	28.10.2024 14:30 GMT				
Prepared by	Jerry Widdas				
Location	Llanblethian				
Personnel					

Audit	7 / 8 (87.5%)
GENERAL SITE DESCRIPTION	1 / 1 (100%)
Detail: Llanblethian Play Area is an open playing field in a quiet area of the town, the play area is accessed across grass from the access gates located on the road. The play equipment has been installed within the past few years and is all in very good condition and installed onto rubber safety surfacing Lappset multiplayer unit installed April 2018 Lappset flat seat swing installed April 2018 Lappset nest swing installed April 2018 Lappset spring rockers installed April 2018 Bank slide installation date unknown Football goal installed June 2023 Ball shoot installation date unknown	Yes
         	
ITEM	6 / 6 (100%)
Manufacturer identification and date of installation All play equipment listed above	Yes
Item Condition	Safe
Safety Surfacing A moss killer was applied Moss starting to disappear	Safe
  	

Equipment Findings

Safe

The vehicle access gate has recently been replaced, the pedestrian gate remains. Capstones on the gate pillars are very loose and falling off, these continue to get worse



Photo 14



Photo 15



Photo 16

Safety Surfacing Findings

Safe

All safety surfaces are in good condition with no damage showing

Recommendations

Yes

Schedule inspection for 15th November

Other comments

0 / 1 (0%)

Inspector Sign Off

Jeremy Widdas OP9635
30.10.2024 20:30 GMT

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16