

Play Area / Equipment Operational Inspection

LLANBLETHIAN PARK PLAY AREA

Complete

Score	7 / 8 (87.5%)	Flagged items	0	Actions	0
-------	---------------	---------------	---	---------	---

Document No. 000013

Audit Title LLANBLETHIAN PARK PLAY AREA

Client / Site COWBRIDGE TOWN COUNCIL

Conducted on 31.10.2025 19:00 GMT

Prepared by Jerry Widdas

Location Llanblethian

Personnel

Audit

7 / 8 (87.5%)

GENERAL SITE DESCRIPTION

1 / 1 (100%)

Detail:

Yes

Llanblethian Play Area is an open playing field in a quiet area of the town, the play area is accessed across grass from the access gates located on the road.

The play equipment has been installed within the past few years and is all in very good condition and installed onto rubber safety surfacing

Lappset multiplayer unit installed April 2018

Lappset flat seat swing installed April 2018

Lappset nest swing installed April 2018

Lappset spring rockers installed April 2018

Bank slide installation date unknown

Football goal installed June 2023

Ball shoot installation date unknown



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6




Photo 7



Photo 8



Photo 9



Photo 10

ITEM

6 / 6 (100%)

Manufacturer identification and date of installation

Yes

All play equipment listed above

Item Condition

Safe

As Winter draws in timber surfaces can become very slippery as per the access climber




Photo 11

Safety Surfacing

Safe

Moss treatment has been applied



Photo 12

Equipment Findings

Safe

The vehicle access gate has recently been replaced, the pedestrian gate remains.

Safety Surfacing Findings

Safe

All safety surfaces are in good condition with no damage showing

Recommendations

Yes

Schedule inspection for 27th October

Other comments

0 / 1 (0%)

No

Inspector Sign Off

Jeremy Widdas OP9635
11.11.2025 20:53 GMT

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12